Work Orde January 25, 201												Page 1
Revision ID:	D3826-041 Rib / Gusset A	ssembly		Accept			Setup	Start Stop	i ibeliibi e			
Start Date: 1/25/10 Start Qty: 6.00 Required Date: 1/29/10 Req'd Qty: 6.00 Reference:  Approvals: Process Plan: QC:					Cust Item ID: Customer:					118811181		
		Date:/// -/-2	Tooling: SPC (Y/N):		Date:Date:			Run	Start Stop			
Sequence ID/ Work Center II	)	Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accep Qty	t Rej Qty	ject	Reject Number	Insp. Stamp
Draw Nbr	Rev	ision Nbr		<del></del>				:				
D3826	Rev	В										
100 Large Fab		Large Fab		0.00				S	M,	0/0	2/01	E CE

110

QC9- Inspect visual per QSI004- Fusion Welds

rib and weld as per dwg D3826 A/R ER316 S.S. Rod Batch: 413338

0.00

Memo

0.00

D 10.02.01 @

Quality Control

120

Memo

QC5- Inspect part completeness to step on W/O

) => S (olozlo)

Quality Control

Dart Aerosp	pace Ltd
-------------	----------

W/O:		WORK ORDER CHANGES												
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
				,										
Part No	•	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DG	A:	_ Date: _						
			on: Disposition:											
NCR:			WORK ORDI	ER NON-CONFORMA	ANCE (NC	R)								
DATE	OTED	Description of NC	Corrective Action Section B			Verif	cation	Approval	Approval					
DATE	SIEP	STEP Description of NC Section A		Initial Action Description Chief Eng Chief Eng			tion C	Chief Eng	QC Inspector					
						:								
								}						
									E					

#### Work Order ID 55618

January 25, 2010 12:35:49 PM



Page 2

Item ID:

D3826-041

Accept

Setup Start

Stop



**Revision ID:** 

Item Name:

Rib / Gusset Assembly

**Start Date:** 

1/25/10

QC:

Start Qty: 6.00

Req'd Qty: 6.00



**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

**Process Plan:** 

Date: Date:

**Tooling:** 

Date:

Start

Required Date: 1/29/10

SPC (Y/N):

Date:

Stop

Sequence ID/ Work Center ID

130

Packaging

Operation Description

Identify as per dwg & Stock Location:

Set Up/ **Run Hours** 

0.00

Draw

Number

Rev.

Draw Plan Code

Accept Oty

Reject Qty

Reject Number Stamp

Insp.

140

Packaging

Memo

0.00

PD 10.02.01

Run

Quality Control

Memo

QC21- Final Inspection - Work Order Release

0.00

0.00

10/02/02/9 MF 10-2-01

W/O:			WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CHAN	IGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
								,						
					E									
Part No			: Fault Category: N											
	R	esolution:	Disposition	l:	QA:	N/C Cld	sed:		Date:					
NCR:			WORK ORDE	R NON-CONFORMA	NCE	(NCR	)			•				
DATE	OTED	Description of NC		Corrective Action Section	n B		Verific	ation	Approval	Approval				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti		Chief Eng	QC Inspector				
	-													
-									•					
		·												
									- Forda					

### **Picklist Print**

January 25, 2010 12:35:55 PM

Work Order ID: 55618

Parent Item: D3826-041

Parent Item Name: Rib / Gusset Assembly

IPP Rev:A 08-12-01 new issue DD verified by:EC Comments:

Manufactured

**Start Date: 1/25/10** 

Start Qty: 6.00

Required Date: 1/29/10

Required Qty: 6.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2235-1		Manufactured	No		<del></del>		Each	12.0000	6.0000			

Basket Rib

Warehouse	Loc Qty	Loc Code			
Location  Main Warehouse		54864		ax	
WA	12				
50565	3				IM.
54206	9			<u>Чх</u>	M 10/01/a8
	Each	11.0000	6.0000		4 - 1-1140

Loc Code

D3929-041

Gusset Assembly

Loc Qty Warehouse Location Main Warehouse WA 11 53675 2 54729

<b>Dart Aeros</b>	pace Ltd
-------------------	----------

W/O:		WORK ORDER CHANGES												
DATE	STEP	PR	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
<del>1</del>														
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes	No DQ	A:	Date: _						
	Re	esolution:	Disposition	:	QA: N/C C	losed:		Date: _	·					
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCI	₹)								
DATE	STEP	Description of NC Section A	Corrective Action Initial Action Descr		etion B Sign	Verification Section C		Approval Chief Eng	Approval QC Inspector					
			Chief Eng	Chief Eng	Date	Jecii		Office Ling	QO mapecioi					
								ļ						
					····	•								
	1													

#### **Picklist Print**

January 25, 2010 12:35:55 PM

Work Order ID: 55618

Parent Item:

D3826-041

Parent Item Name: Rib / Gusset Assembly

Comments:

IPP Rev:A 08-12-01 new issue DD verified by:EC

Manufactured



Start Date: 1/25/10

Start Qty: 6.00

6.0000

Required Date: 1/29/10

Required Oty: 6.00

Component Item ID/ Item Name

Replacement Mfg/ Item ID

Purch

Bin Primary Item Location

No

Last Location

54730

Route Seq ID

Unit of Measure

Each

Oty on Hand

25.0000

Remaining Oty Qty To Pick Issued Date Issued

Status

Page 2


D3929-042

Gusset Assembly


Warehouse Loc Qty Loc Code Location · Main Warehouse ST 16 50567 2 50869 53969 Main Warehouse WA

5x M 10/01/28

W/O:	WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CHA	ANGE	Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
									•			
						+						
							_					
Part No	•	PAR #:	Fault Cate	egory:	NCR: Yes No DQA: Date:							
		esolution:										
NCR: WORK ORDER NON-CONFORMAN									<del></del>			
DATE	STEP	Description of NC		Corrective Action Section			Verific	ation	Approval	Approval		
DAIL	SILF	Section A	Initial Chief Eng			n & ate	Section C		Chief Eng	QC Inspector		
<u> </u>												



	•								
W/O:			W	ORK ORDER CHANG	ES	·			
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	Date: _	
Resolution:			Dispositio	n:	_ QA: N/C C	losed:		Date: _	
NCR:	WORK ORDER NON-CONFORMANCE (N					₹)			
DATE	STEP	Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval
DATE	SIEP	Section A	on A Initial Action Des Chief Eng Chief E		Sign Date			Chief Eng	QC Inspector
,									
į.									
						-			
	i.			·					
5									
	1					1			Į.



W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
				-									
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	<b>A</b> :	_ Date: _					
		olution:											
NCR:			WORK ORDE	ER NON-CONFORMA	NCE (NCF	?)							
DATE	STEP	Description of NC	Initial	Corrective Action Section	on B Sign &		cation	Approval	Approval				
		Section A	Chief Eng	Action Description Chief Eng	Date	Secti	on C	Chief Eng	QC Inspector				
•													
								-					
		•											